

General Job Information...

Reported By	Iceland St Peter	Phone	Iceland St Peter
Email	store150@sandpiperCI.com	Department	
Order/Cust No.		Start Date/Project ID	11/05/2021 10:30 / 0
Cost Code		Est Comp. Date/Time	13/05/2021 10:30:00
Contract		Completion Date	
Created By	Della Bagnall	Date Created	11/05/2021 10:33:00
Client	Iceland	Building	Iceland St Peter La Rue de l'Eglise, St Peters Village St Peter Jersey JE3 7AG 767478

Location Area

Job Location	Est Resp. Date/Time
---------------------	----------------------------

Job Details...

Worker	CP Sunblinds	Current Status	Open
Work Type	General Maintenance	Job Description	Miscellaneous
Priority	Normal		
Comments	on our front window can I have a solar shade put on to the window (not entire window just about 20cm high) to stop sunlight hitting stock on the other side. Can you please provide a quote to della		

Record New Response Information...

Job Complete?	<input type="text"/>	Completed	<input type="text"/>
Date Started	<input type="text"/>	Asset Details	<input type="text"/>
Time Started	<input type="text"/>	Status Level	<input type="text"/>
Time Spent (Hrs)	<input type="text"/>		
Comments	<input type="text"/>		
Worker Name & Signature	<input type="text"/>		

ANY ORDERS EXCEEDING £1000 MUST SEEK AUTHORISATION FROM THE PROPERTY DEPARTMENT BEFORE CARRYING OUT WORKS.

THE CONTRACTOR SHOULD BE AWARE THAT ASBESTOS MAY BE PRESENT ON SITE. IF IN ANY DOUBT, THEY SHOULD CONTACT THE SITE MANAGER FOR FURTHER INFORMATION.

BEFORE CARRYING OUT ANY WORKS, PLEASE PROVIDE A RISK ASSESSMENT AND METHOD STATEMENT.