

Order For Service/Repair

Supplier		Invoice Details		Delivery Details	
Order No.	SO12057	Name	Mr & Mrs. Andrew & Tracy Clarke	Name	Mr & Mrs. Andrew & Tracy Clarke
Customer Ref.		Address	Wood End La Route Orange	Address	Wood End, La Route Orange
Contact Tel.	01534 768141		St Brelade		St Brelade
Date of Order	04-08-2021	Postcode	JE3 8GP	Postcode	JE3 8GP
Date Required	15-12-2021	Phone	822391	Phone	822391

Supplier		Invoice Details	
Order No.	SO12057	Name	Mr & Mrs. Andrew & Tracy Clarke
Customer Ref.		Address	Wood End La Route Orange
Contact Tel.	01534 768141		St Brelade
Date of Order	04-08-2021	Postcode	JE3 8GP
Date Required	15-12-2021	Phone	822391

Qty	Location	Description
1		Blind in master bedroom does not go up any more. and bottom bar of spare room blind is off

Date	Issue & Action	Arrival Time	Departure Time	Fitter(s)	Hours Spent	Parts Required	Cost £
16/6/22	brought back roller to change bottom bar fixing	14:00	14:30	AB	30mins		
17/6/22	changed roller to stop bottom rail from falling off TROPICAL BLINDS!			Steve	1/2 hr		
20/6/22	re-titted roller & gave 2x battery packs to charge Remains as none left on org install	Arr 1:30	2:00	ATB	30M		
Total:							

(Signature)

Warranty