**Staff Name** Adrian

# Work Diary

| Order No | Measurer or Fitter | Contact Address | Customer Ref | Date | Time |
|---|---|---|---|---|---|
| SO12346 | Measurer | Mr & Mrs.Heather & Anthony Doull, 5 Links Court, Rue A Don, Grouville, JE3 9DZ, 732538, heatherdoull@icloud.com | | 14-09-2021 | 15:30 |

**Notes :** curtain track to replacement existing one not strong enough

| Location | Supplier | Blind Type /Description | Colour | Qty | Width | Drop | Fitting Height | Blind/Recess | Controls | Brackets | Surface | Unit Price |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SPARE Bed | | Cord op Curtain Track SS 3900 | | 1 | 3400 | | split | LH Cord | | TOP | | 259 |
| Bed | | with wheeled gliders | | 1 | 3580 | | a | LH Cord | ~ | | | 286+? |

| Comments: | Order Date | Customer Signature<br>X<br>I have checked and agree with the above choices |
|---|---|---|
| | | Target Fitting Date |