Order For Service/Repair

INV: 7723 5-11-21

Supplier	C P
Order No.	SO12402
Customer Ref.	
Contact Tel.	01534 768141
Date of Order	28-09-2021
Date Required	03-11-2021

Invoice Details	
Name	Mr & Mrs. Richard Guillard
Address	La Cloyere Rue de la Lourderie
	St Clement
Postcode	JE2 6SG
Phone	852537

Delivery Details	
Name	Mr & Mrs. Richard Guillard
Address	La Cloyere, Rue de la Lourderie
	St Clement
Postcode	JE2 6SG
Phone	852537

Qty	Location	Description
1		Picked up roller blind and brought back to workshop. Blind fabric had broken off bottom rail. Made a new bottom pocket. 24.09.21
1		Re-fitted roof roller blind & changed two pulleys. 02.11.21

Date	Issue & Action	Arrival Time	Departure Time	Fitter(s)	Hours Spent	Parts Required	Cost £
24/9/21	Pickuproller blind. Fabric has broken off bottom rail.	8AM	8-15AM	SteveB	15 Mins		£55
24/9/21	Make new bottom Pocket	//	//	SteveB	15Mins		
2/11/21	Re-fit roof roller blind & change two pulleys.	8AM	9AM	SteveB	1 Hour		£55
						Total:	£110 +GST