



SUB-CONTRACTORS JOB WORK REPORT

CLIENT NAME/SITE: REGUS	TASK ID: 323PJ:00188
-------------------------	----------------------

DATE: 19/01/22	ARRIVAL TIME: 15-00	DEPARTURE TIME: 15-45
----------------	---------------------	-----------------------

TASK DESCRIPTION:
look at damaged blind
measure for new one

ENGINEERS COMMENT:
parts missing recommend replacement

CLIENT SIGNATURE:



PRINT NAME:

Julietta Joaquin

PLEASE GET THE JOB WORK REPORT SIGNED AND SCANNED BACK TO AFM SERVICE DESK ON COMPLETION

FAILURE TO COMPLY WITH THIS CLIENT REQUEST WILL RESULT IN LATE OR NON PAYMENT OF WORKS