Order For Service/Repair

Supplier	**C P**
Order No.	**SO13881**
Customer Ref.	**4 Le Printemps, La Rue Du Val, St Martin, JE3**
Contact Tel.	**01534 768141**
Date of Order	
Date Required	

Invoice Details	
Name	Ms. Julie Leventhal
Address	Le Camelia 2 Le Catelet
	La Route De St Jean
	St John
Postcode	JE3 4EN
Phone	

Delivery Details	
Name	Ms. Julie Leventhal
Address	Le Camelia , 2 Le Catelet
	La Route De St Jean
	St John
Postcode	JE3 4EN
Phone	

Qty	Location	Description
1	Ben's Bedroom	Multi shade blind - bottom bar has come off. needs repairing - 01452 922281 - 021G SG 6982

Date	Issue & Action	Arrival Time	Departure Time	Fitter(s)	Hours Spent	Parts Required	Cost £
13/10/22	new fabric needed (7062 fabric)	9:30	10.30	AB	45mins		
						Total:	

Appointment For	Andy	From	13-10-2022	To	13-10-2022

Thursday **13-10-2022**

08:30 AM			Ms. Wendy Durell, , La Maison Es Allures , La Rue Des Allures , Grouville , , JE3 9AJ, 854661, 07715 566 755 wendy@wendydurell.co.uk	
SO13808	Measurer	18	Rachel has asked to check measure on living room/dining room curtains. request of client. Please see Scott before you go	
09:30 AM	(Smarett)		Ms. Julie Leventhal, , Le Camelia , 2 Le Catelet, La Route De St Jean, St John, JE3 4EN, 07797785145 jkleventhal@gmail.com	
SO13881	Fitter	1	Ben's Bedroom 1 x Service/Repair 0 by 0 Multi shade - bottom bar has come off fabric Replacement	4 Le Printemps, La Rue Du Val, St Martin, JE3 6ER
10:30 AM			Mrs. Susan Morin, , Alameda , 4 Jardin De La Reine , La Grande Route De Faldouet , St Martin , JE3 6UG, 07797732145, susan.morin1@hotmail.com	
SO10556	Fitter	11	issue with sotteza shuddering. BR knows with Ben	Glasshouse
11:30 AM				
	Deliver		Deliver various to Roger for alterations SO13587 Oliveira - 1 x Roman to be adjusted SO13756 Trevellyan - curtains SO13077 Williams - Roman cut corners Hern - curtains adjustment	
12:30 PM				
	Holiday		~~TEST only re-BM issues~~	
13:00 PM			Mrs. Emma Mccue, , La Pezerie, La Rue De Platons, Trinity, JE3 5AA, 07829967281, nicolea.wheatley@gmail.com	
SO13875	Fitter	1	1 x Service/Repair 0 by 0 3 x rollers not going up (manually operated)	
14:00 PM			Mr. Hallett, , Pre Des Bacasse , Longueville Road , St Saviour , , JE2 7WG, 722372, pwhalt@gmail.com	
SO13842	Fitter	1	1 x Service/Repair 0 by 0 remove awning, store on site. bind with timber, wrap in plastic - store by poolside.	Sandra 07797781005

1 x bottom bar end cap left side

(xpoice called fabric repair refit)

Spare bed fabric

fell apart B/S 1440 x 1000

fabric size 1410

SO13881 Leventhal

master bed 1885 x 2250 B/S fabric size 1850

fabric ripped

Bed 1 fabric ripped 1850 x 2250 B/S fabric size 1850