



# SUB-CONTRACTORS JOB WORK REPORT

<b>CLIENT NAME/SITE:</b> Regus 119	<b>TASK ID:</b> 823PJ00305
---------------------------------------	-------------------------------

<b>DATE:</b> 30/5/23	<b>ARRIVAL TIME:</b>	<b>DEPARTURE TIME:</b>
-------------------------	----------------------	------------------------

**TASK DESCRIPTION:**  
Repair blind x Return to refit  
  
CP INTERIORS.

**ENGINEERS COMMENT:**

<b>CLIENT SIGNATURE:</b> 	<b>PRINT NAME:</b> JASMINE
------------------------------	-------------------------------

PLEASE GET THE JOB WORK REPORT SIGNED AND SCANNED BACK TO AFM SERVICE DESK ON COMPLETION  
FAILURE TO COMPLY WITH THIS CLIENT REQUEST WILL RESULT IN LATE OR NON PAYMENT OF WORKS



# SUB-CONTRACTORS JOB WORK REPORT

CLIENT NAME/SITE: <i>Regus 119</i>	TASK ID: <i>3230 J 00305</i>
---------------------------------------	---------------------------------

DATE: <i>30/5/23</i>	ARRIVAL TIME:	DEPARTURE TIME:
-------------------------	---------------	-----------------

TASK DESCRIPTION:  
*Repair blind x Return to refit*

*CP INTERIORS.*

ENGINEERS COMMENT:

CLIENT SIGNATURE: <i>[Signature]</i>	PRINT NAME: <i>JASMINE</i>
---	-------------------------------

PLEASE GET THE JOB WORK REPORT SIGNED AND SCANNED BACK TO AFM SERVICE DESK ON COMPLETION  
FAILURE TO COMPLY WITH THIS CLIENT REQUEST WILL RESULT IN LATE OR NON PAYMENT OF WORKS