

Staff Name: Adrian

Work Diary.

Order No: SO16907
Surveyor: Measurer

Contact Address:

Mrs.Susan Morton Hawk House , Park Estate , La Route Des Genets, St Brelade, JE3 8EQ,
07797746286. smortonjersey@gmail.com

Customer Ref:

26-06-2025

Time:

10:00 AM

Notes : To measure to upgrade electric curtain tracks as they have failed and are obsolete

| Location | Supplier | Blind Type /Description | Colour | Qty | Width | Drop | Fitting Height | B or R | Controls | Brackets | Surface | Unit Price |
|----------|----------|-------------------------|--------|-----|-------|------|----------------|--------|----------|----------|---------|------------|
| WASH | SS | Replacement | | 2 | 1500 | | | R | Remote | td | | |
| Sea | | S/S | | | | | | H | | | | |
| | | Electric Track | | | | | | Mobor | | | | |
| | | new remote | | | | | | 6 | | | | |
| | | Pairs | | | | | | Both | | | | |
| Kitchen | SS | Remote Track | | 1 | 880 | 2160 | | | | | | |
| Lv | | | | 1 | 1600 | 2160 | | | | | | |
| Area | | | | 1 | 1600 | 2160 | | | | | | |
| | | | | 1 | 880 | 2160 | | | | | | |
| 4 | h | Replacement | | 1 | 3400 | | | B | Remote | td | | |
| | | Track | | | | | | | | | | |
| | | 1 pair | | | | | | | | | | |

Comments:

PH

Surface Fixing
 C=Concrete
 W=Wood
 M=Metal
 B=Brick
 P-Plastic
 T=Tile

Order

Customer Signature

X

I have checked and agree with the above choices

Quote

Target Fitting Date