Staff Name Adrian

Order No	Surveyor	Contact Address	Customer Ref	Date	Time
SO17033	Measurer	Mary Clode Le Senechal Rue De La Lourderie Grouville JE3 9SG 871120 maryclode0@gmail.com		05-08-2025	14:00 PM

Account Manager: Scott

Notes : Client has a duorol blinds - she sent photos and said the top metal bar has broken. showed Andy eh said hard to know, fabric may be too far gone to salvage - quite old blinds, fabric may be discontinued, was not on her or previous owner account history

Location	Supplier	Blind Type /Description	Colour	Qty	Width	Drop	Fitting Height	B or R	Controls	Brackets	Surface	Unit Price
Nursery				1	1075	1740		B/P	RHC	Frame		

Comments:

Surface Fixing
C=Concrete
W=Wood
M-Metal
B=Brick
P-Plastic
T=Tile

Order

Quote

Customer Signature
X
I have checked and agree with the above choices

Target Fitting Date