Staff Name Adrian

Order No	Surveyor	Contact Address	Customer Ref	Date	Time
SO17232	Measurer	Health Plus Health Centre Samantha . Queens Road St Helier JE2 4HY 733322 healthplus@healthplus.gpnet.je	Consulting Room 8	06-10-2025	11:30 AM

Account Manager: Tamara

Notes : late morning. blind in room not working may need replacement rather than repair? Only day we can get in

Location	Supplier	Blind Type /Description	Colour	Qty	Width	Drop	Fitting Height	B or R	Controls	Brackets	Surface	Unit Price
ROOM 8		Woodstar		1	1960	650		Rec	SMW	TP		
		SUGGESTED 50mm	off white									

Comments:

Surface Fixing
C=Concrete
W=Wood
M-Metal
B=Brick
P-Plastic
T=Tile

Order

Quote

Customer Signature
X
I have checked and agree with the above choices

Target Fitting Date