Staff Name Adrian

Order No	Surveyor	Contact Address	Customer Ref	Date	Time
SO17226	Measurer	Geoff And Jane Taylor 11 Clos De Noirmont St Brelade JE3 8AP taylorsat11@icloud.com07797746162	Conservatory Account Manager: Tamara	29-10-2025	09:00 AM

Notes : Client has two sails but it is not enough, they want more in the centre. Please advise if there are other options.

See Over

Location	Supplier	Blind Type /Description	Colour	Qty	Width	Drop	Fitting Height	B or R	Controls	Brackets	Surface	Unit Price
		Duette	opaque	1	24/80	310		B	R	Top		
		cord op										
		Soil shades	Solid	2	AS	over	AS					
			oyster			in shade if	They have					
						drawings	from previous					
							order					
						Client not	sure if it was					
						us.						

Comments:

PINK recieved 29/10

Surface Fixing
C=Concrete
W=Wood
M-Metal
B=Brick
P-Plastic
T=Tile

Order

Customer Signature
X
I have checked and agree with the above choices

Quote

Target Fitting Date



Existing

New

2 Sails

Full Coverage