Staff Nar. Adrian

Order No	Surveyor	Contact Address	Customer Ref	Date	Time
SO17585	Measurer	George Demetriou La Chasse La Chasse Brunet St. Saviour george.demetriou@gmail.com07829 707270		13-02-2026	11:00 AM

Account Manager: Scott

Notes : Client has a velux in master bed that needs replacing, told him beyond repair and would like a replacement - he sent a photo but he did not want to commit on the colour - look sbeige or white - said best to check before qoting/ordering - also has velux in en suite - wants us to check to see if needs replacing also

Location	Supplier	Blind Type /Description	Colour	Qty	Width	Drop	Fitting Height	B or R	Controls	Brackets	Surface	Unit Price
Bed	Velux	Velux	~~CK~~	1	CK	04						
		Siesta roller	magnolia B/O		SSL							

Comments:

Surface Fixing
C=Concrete
W=Wood
M-Metal
B=Brick
P-Plastic
T=Tile

Order

Quote

Customer Signature
X
I have checked and agree with the above choices

Target Fitting Date