

Staff Name: Adrian

Order No: SO17672  
Surveyor: Measurer

Contact Address: S Hollywood  
Broadfields Rue Des Boulees Trinity JE3 5HN kattriona\_hollywood@yahoo.co.uk 07797725869  
851522

Customer Ref

Date: 06-03-2026

Time: 11:00 AM

Account Manager: Scott

Notes: client phoned to say wood venetians have broken, slats, strings etc - was keen on replacements if cannot be repaired - i looked for history on the installation but think they are old

AM Approx

Location	Supplier	Blind Type /Description	Colour	Qty	Width	Drop	Fitting Height	B or R	Controls	Brackets	Surface	Unit Price
Bed 1		Plant AS	TISA	1	425	700	0071 R		41.4 L-50			
		previous		1	840	1295			L-76			
				1	1025	1055			L-76			
Bed 2				1	1030	1120			L-60			
				1	960	1340			L-60			
					See over							

Comments:

Surface Fixing  
C=Concrete  
W=Wood  
M=Metal  
B=Brick  
P=Plastic  
T=Tile

Order


Quote

Customer Signature

X

I have checked and agree with the above choices

Target Fitting Date



Bed 1 and 2  
2 triangular slabs  
each room  
ft