Staff Name Adrian

Order No	Surveyor	Contact Address	Customer Ref	Date	Time
SO17739	Measurer	C And A Bambury St Anthony Norcott Road St Saviour JE2 7PS jerseypiglet@hotmail.co.uk734198	Vertical Blind Account Manager: Tamara	30-03-2026	14:00 PM

Notes : To assess vertical blind damaged by cat to see if it can be repaired or measure for new one.

Location	Supplier	Blind Type /Description	Colour	Qty	Width	Drop	Fitting Height	B or R	Controls	Brackets	Surface	Unit Price
~~FF~~ Dining		Vertical 89m	White	1	1255	1980		R	RH	TOP		
room			Edipse						+ stack			
T/V		"	chenille	1	3015	2045		R	spin	FACE		
room			snowcap									
Study		"		1	900	1850		R	RH	TOP		
"				1	1130	1850		R	+ stack	"		
		please email photo of fabric THANK										

Comments:

Surface Fixing
C=Concrete
W=Wood
M-Metal
B=Brick
P-Plastic
T=Tile

Order

Quote

Customer Signature
X
I have checked and agree with the above choices

Target Fitting Date