

DIRECT BLINDS - SANTA FE SHUTTER SURVEY

CAN WE DO MARION

Name	COLLETTE DINIUS
Address	7 CHAPEL FIELD KNOXBERA
Date	10-2-22
TC No.	7174

Range	NAVADA OR HAMPER
Color	VIVID WHITE
Additional work	Sketching to be remade out back if possible.

Additional Information / Requirements	Doors must be less than 550 Kelsey -
---------------------------------------	---

No.	Room	Width	Height	Panel Layout	Shutter Type	Shutter Design	Louver size	Midrail	Tilt Option	Frame Type	Frame				Style	T Post	Batton	
											Left	Right	Top	Bottom				
1	8.849	2905	2105	3-3R	STD.	Full Height.	76"	YES	Option TILT BAR.	DZ25 Deluxe 2 frames	✓	✓	✓	ND	STD AS	No	No	
2																		
3																		
4																		
5			2315															
6																		
7																		
8																		

Handy Room Fitted.

11005 to be fitted

WANTS 3 RIFOLD DOORS.

No.	Room	Post 1	Post 2	Post 3	Post 4
1	8.849	960	1947		

No.	Room	Break 1	Break 2	Break 3	Break 4

No.	Room	Height
1	8.849	860

I am happy with the information carried out in the survey, and I understand that no changes can be made once ordered and there is no refund of deposit.

Customer Signature

DATE ORDERED

Diagrams / Sketches P.T.O.

I SAVE BANK of 62200 See JVF.

E 1395

parameters when floor fitted.