

Fault Report

Customer Name: Young	Date: 25/7/22
Customer Reference: 6096	Fitter: Mark E
Salesperson: 11	Salesperson called: Yes/No
Blind Type and number: Wooden Venetian 1765 x 1420	
Fault Description: Pull cord snapped	
Action to correct: Re-string blind - @ GC for collection.	
Problem fixed on site: Yes/No	
Further action required:	