

GC 6349
Turner./R

Fault Report

Customer Name: Turner	Date: 16/8/22
Customer Reference: 6349	Fitter: Mike
Salesperson: Mike	Salesperson called: Yes/No <input checked="" type="radio"/>
Blind Type and number: 1 x Roman + Curtains	
Fault Description: Fabric flaws - fabric loops + pulls	
Action to correct: TBD - Images sent in - possible remake?	
Problem fixed on site: Yes/No <input checked="" type="radio"/>	
Further action required: Ordered @	