

GC 5677

Allison. R

Fault Report

Customer Name: Allison	Date: 20/7/22
Customer Reference: 5677	Fitter: Mike
Salesperson: Marie e	Salesperson called: Yes/No <input checked="" type="radio"/>
Blind Type and number: Zx Vision	
Fault Description:	
Action to correct: Customer wants the stone coloured fabric on the headrail and doesn't want anymore holes in the window so chains need to be 1130mm from top of blind to bottom of the chain.	
Problem fixed on site: Yes/No <input checked="" type="radio"/>	
Further action required:	