

# Fault Report

Customer Name: Miller	Date: 22/7/22
Customer Reference: 6333	Fitter: Mike
Salesperson: Mike	Salesperson called: Yes/No
Blind Type and number: P Fit Roller	
Fault Description: Blind running 5mm off the square - unable to resolve onsite - Tried to adjust tracking. Due to this fabric appears rippled.	
Action to correct: Resolve blind squareness and re-cover if required.	
Problem fixed on site: Yes/No	
Further action required:	