


5689

# Fault Report

Customer Name: McGinness	Date: 7-9-22
Customer Reference: GC 5689	Fitter: DAVID
Salesperson:	Salesperson called: Yes/No
Blind Type and number:	
Fault Description: REPLACEMENT BLIND WARPED	
Action to correct: 	
Problem fixed on site: <del>Yes</del> /No	
Further action required: NEW BLIND NEEDED	