

GC 5696.

Fault Report

Customer Name: Kerr	Date:
Customer Reference: 25696	Fitter: EA David
Salesperson: Mike	Salesperson called: Yes/No
Blind Type and number: 2 Roller	
Fault Description: Luv middle roller fell down + Damaged Fab Bed FR Right Roller frayed	
Action to correct: Remake both.	
Problem fixed on site: Yes/No	
Further action required:	