

Fault Report

Customer Name: <u>BEATTIE</u>	Date: <u>1-12-22</u>
Customer Reference: <u>6626</u>	Fitter: <u>DAVID</u>
Salesperson: <u>DAVID</u>	Salesperson called: <u>Yes/No</u>
Inputting Error <input type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Blind Type and number: <u>① WOOD</u> ^{FAUX}	
Fault Description: <u>BLIND HAS 3 TAPES ON IT BOT THE REST OF THE SIDE BUT BLINDS HAVE 2 TAPES</u>	
Action to correct:	
Problem fixed on site: <u>Yes/No</u>	
Further action required: <u>RE MADE WITH JUST 2 TAPES</u>	

