

CIC 6489 /
6473

Fault Report

Customer Name: BATCHelor	Date: 5-12-22
Customer Reference:	Fitter: DAUD
Salesperson: MARK	Salesperson called: Yes/No
Blind Type and number: Roller G	
Fault Description: BLIND DAMAGED	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required: NEW BLIND NEEDED CAN THIS BE MADE AT 815 X 1030 RECESS SIZE PLEASE	