

# Fault Report

Customer Name: <u>Sweeney</u>	Date: <u>19-12-22</u>
Customer Reference:	Fitter: <u>DAVID</u>
Salesperson:	Salesperson called: Yes/No
Inputting Error <input type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input checked="" type="checkbox"/>	Supplier Error <input type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Blind Type and number: <u>PERFECT FIT POWERS</u>	
Fault Description: <u>BOTTOM PART OF FRAME 3MM WIDER THAN TOP PART ON BOTH BLINDS</u>	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required: <u>2 NEW BOTTOM PARTS OF FRAME AT <del>447</del> 447</u>	