

✓ GC 6849
FLYNN/RS

Fault Report

FITTER NAME: David	FITTING DATE: 26/08/24
Customer Name: Flynn	
Customer Ref: 6849	
Salesperson: David	Salesperson called: Yes/No
Blind Type and number: Intu rollers 1 and 2	
Problem fixed on site: Yes/No	
Fault Description Blinds have been made with material in wrong direction	
Action to Correct:- New blinds with material going horizontal	