

GC 7143

MCCREATH/R

Fault Report

Customer Name: <u>MCCREATH</u>	Date: <u>22-8-23</u>
Customer Reference: <u>7143</u>	Fitter: <u>DAVID</u>
Salesperson: <u>DAVID</u>	Salesperson called: Yes/No
Inputting Error <input type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Blind Type and number: <u>Bed 1 RF 1x2 LHS FRAME .</u>	
Fault Description: <u>LHS FRAME MARKED</u>	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required: <u>NEW LHS FRAMES (FITTED ON SITE)</u>	