

Fault Report

Customer Name: Cobby	Date: 30/11/23
Customer Reference: 7066	Fitter: David
Salesperson: Graeme	Salesperson called: Yes/No
Blind Type and number: roller	
Fault Description: No fitting height so chain made to small	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required: New continuous plastic chain with a fitting height of 2400	