

41 6849  
FLYNN / R

## Fault Report

FITTER NAME: David	FITTING DATE: 16/7/24
Customer Name: Flynn	
Customer Ref: 6849	
Salesperson: David	Salesperson called: Yes/No
Blind Type and number: 2 x Intu Rollers	
Problem fixed on site: Yes/No	
Fault Description Side channels sent are too big so blind does not fit	
Action to Correct:- Send smaller side channels (Medium ones)	