

GC 7677
HASTINGS / R
010027547R

Fault Report

FITTER NAME: David	FITTING DATE: 22/8/24
Customer Name: Hastings	
Customer Ref: 7677	
Salesperson: David	Salesperson called: Yes/No
Blind Type and number: Lounge wood venetian	
Problem fixed on site: Yes/No	
Fault Description Pelmet damaged Picture sent in	
Action to Correct:- New pelmet needed	