

GC 7301
WILLIAMSON/R

Fault Report

FITTER NAME: David	FITTING DATE: 22/8/24
Customer Name: Williamson	
Customer Ref: on027562 GC 7301 WILLIAMSON	
Salesperson:	Salesperson called: Yes/ <u>No</u>
Blind Type and number: Vertical slat	
Problem fixed on site: Yes/ <u>No</u>	
Fault Description Got asked to take size of slats as some missing	
Action to Correct:- New slats at 2075 hem to hem	