

# Fault Report

UC 7525  
HARROLD / R  
ON27722R

<b>FITTER NAME:</b> David	<b>FITTING DATE:</b> 14/11/2024
<b>Customer Name:</b> Harrold	
<b>Customer Ref:</b> 7525	
<b>Salesperson:</b> Ronnie	<b>Salesperson called:</b> Yes/No
<b>Blind Type and number:</b>  Vertical slats	
<b>Problem fixed on site:</b> Yes/No	
<b>Fault Description</b>  The slats have been made recess size instead of hem to hem	
<b>Action to Correct:-</b>  New slats needed at hem to hem size	