

GC 7427

MCALISTER/K

ON 27 656R

Fault Report

FITTER NAME: David	FITTING DATE: 29/10/24
Customer Name: Mcalister	
Customer Ref: 7427	
Salesperson:	Salesperson called: Yes/No
Blind Type and number: Kitchen left roller & rear bed roller	
Problem fixed on site: Yes/No	
Fault Description Both rollers have pin holes on them Customer paying extra to have black cassette on kitchen left roller	
Action to Correct:- New blinds needed for both.	