

SB 7590
MCLACHLAN/R

ONS 530SR

Fault Report

FITTER NAME: David	FITTING DATE: 11/03/2025
Customer Name: Mclachlan	
Customer Ref: 7590	
Salesperson: Ronnie	Salesperson called: Yes/No
Blind Type and number: Curved vertical slat	
Problem fixed on site: Yes/No	
Fault Description Track damaged	
Action to Correct:- New track needed	