

GC 8022
Law / R.

Fault Report

Customer Name: Law	Date: 29 9 75
Customer Reference: 8022	Fitter: DAVIS
Salesperson: Rowne	Salesperson called: Yes/No
Order Inputting Error <input type="checkbox"/>	Mismeasure <input checked="" type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Problem fixed on site: Yes/No	
Blind Type and number: Hollow	
Fault Description: MIS MEASURE	
Action to correct: Blinds should be 2100 mm - (Eye internal side) (100 mm)	

