

WORK ORDER#: R11287843

Customer

Requestor's Name: Greig Mills	Requestor's Phone#: 0141 330 4457
Customer Level: University of Glasgow - FM Zone 1	Contract: University Of Glasgow UKUJOG / CA003922
Building: WOLFSON LINK BUILDING	
Floor: LEVEL 3	
Area: 362 - RESEARCH OFFICE	
Location w/i Area:	
Notes:	
Dispatcher Name: SI Request SI Request	
Dispatcher Phone:	

Job Instructions

Target Response on Site: 10/30/24 10:16 AM UTC	Priority: P4
Target Completion: 10/30/24 10:16 AM UTC	Billable: No
Date Completed :	
Problem Description: Furniture Damage:>HD.2024100942.1 GROUNDS / RECYCLING - OTHER - PLEASE PROVIDE DETAILS One of the blinds in room 362 of the Wolfson Link building is broken. Can this be fixed please. Many thanks	

Work Summary

Company Name:	25mm VENETIAN (SILVER/GREY)
Technician Name:	
Start: (Date/Time)	2@1680X1950
Work Performed:	
PARTS USED: Qty, brand, model, serial#, cost	End: (Date/Time)
Cost Center Number:	FU 24

Additional Technician Name(s):		End: (Date/Time)
Start: (Date/Time)	€ 488	
Work Performed:		

Notes

:
