

20359
Mayberry R

Fault Report

Customer Name: <u>MAYBERRY</u>	Date: <u>12/5/22</u>
Customer Reference: <u>20359</u>	Fitter: <u>ROSS</u>
Salesperson: <u>Wauker</u>	Salesperson called: Yes/ <input checked="" type="radio"/> No
Blind Type and number: <u>VERT</u>	
Fault Description: <u>Slats too long</u>	
Action to correct: <u>need new Slats.</u>	
Problem fixed on site: Yes/ <input checked="" type="radio"/> No	
Further action required: <u>Yes.</u>	