

Fault Report

Customer Name <i>Field</i>	Date;
Customer Reference: <i>20679</i>	Fitter <i>Walker</i>
Salesperson: <i>WS.</i>	Salesperson called: Yes/No
Fault Description: <i>Charger connection - roller blind.</i>	
Action to correct: <i>Complete blind reprogramme repair roller blind chain</i>	
Problem fixed on site: <input checked="" type="radio"/> Yes / <input type="radio"/> No	
Further action required:	