

Fault Report

Customer Name: Jackson	Date: 14/6/27
Customer Reference: 20617	Fitter: Ross
Salesperson: Martin	Salesperson called: Yes/No <input checked="" type="radio"/>
Blind Type and number: Roman	
Fault Description: measured too big.	
Action to correct: remeasure and remake Size should be 1120 wide drop was fine.	
Problem fixed on site: Yes/No	
Further action required:	

Fault Report

Customer Name: Jackson	Date: 14/6/22
Customer Reference: 20617	Fitter: Ross
Salesperson: Martin	Salesperson called: Yes/No
Blind Type and number: Venetian	
Fault Description: Should be two ordered but with 25mm slats	
Action to correct: order 2 with 25mm slats	
Problem fixed on site: Yes/No	
Further action required: 2 Venetians to be made with 25mm slats	