

Fault Report

Customer Name: Ferguson	Date: 22-9-22
Customer Reference: 20469	Fitter: Amo
Salesperson: Walker	Salesperson called: Yes/No <input checked="" type="radio"/>
Blind Type and number: 20469 Vision	
Fault Description: Wrong fabric	
Action to correct: Re cover OG in window cedar.	
Problem fixed on site: Yes/No <input checked="" type="radio"/>	
Further action required: Yes.	