

Fault Report

Customer Name: Morrison	Date: 21/10/22
Customer Reference: 21327	Fitter: Ross
Salesperson: MC	Salesperson called: Yes/No <input checked="" type="radio"/>
Inputting Error <input checked="" type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Blind Type and number: Roman	
Fault Description: Customer wanted B10 Lining WAS NOT on paperwork	
Action to correct: New Blind	
Problem fixed on site: Yes/No <input checked="" type="radio"/>	
Further action required: Yes	