

Fault Report

Customer Name: <i>drieslick</i>	Date: <i>24-10-22</i>
Customer Reference: <i>21343</i>	Fitter: <i>mc</i>
Salesperson: <i>MC</i>	Salesperson called: Yes/No
Inputting Error <input type="checkbox"/>	Mismeasure <input checked="" type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Blind Type and number: <i>Row</i>	
Fault Description: <i>100 BICr</i>	
Action to correct: <i>needs cut down do .</i> <i>1760 X 1525 Recess</i>	
Problem fixed on site: Yes/ <u>No</u>	
Further action required: <i>Yes</i>	