

# Fault Report

Customer Name: <i>Allan</i>	Date: <i>14/3/23</i>
Customer Reference: <i>22063</i>	Fitter: <i>RB</i>
Salesperson: <i>MC</i>	Salesperson called: Yes/ <input checked="" type="radio"/> No
Blind Type and number: <i>Row</i>	
Fault Description: <i>Mis Measure Too Small.</i>	
Action to correct: <i>needs do be 769 x 970</i>	
Problem fixed on site: Yes/ <input checked="" type="radio"/> No	
Further action required: <i>Yes.</i>	