

Fault Report

Customer Name: DRYBOURN	Date: 15/3/23
Customer Reference: 22003	Fitter: RB
Salesperson: WS	Salesperson called: Yes/No <input checked="" type="radio"/>
Blind Type and number: UNTO	
Fault Description: UNTO hit door TRIED TO CUT DOWN CUT TOO MUCH	
Action to correct: RE ORDERED NEW	
Problem fixed on site: Yes/No <input checked="" type="radio"/>	
Further action required: Yes	