

Fault Report

Customer Name: 22118	Date: 4/4/23
Customer Reference: muddleton	Fitter: MC
Salesperson: MC	Salesperson called: Yes/ <input checked="" type="radio"/> No
Blind Type and number: Vision	
Fault Description: Tried to change fabric on site BUT Roll was too big & fabric ripped	
Action to correct: ordered a remake .	
Problem fixed on site: Yes/ <input checked="" type="radio"/> No	
Further action required: Yes	