

Fault Report

Customer Name: 0123	Date: 13/4/23
Customer Reference: Dawn	Fitter: RB
Salesperson: MS.	Salesperson called: Yes/No
Blind Type and number: senses Pelmet	
Fault Description: made do BIC By factory	
Action to correct: needs do be 2345	
Problem fixed on site: Yes <input checked="" type="radio"/> No <input type="radio"/>	
Further action required: yes.	