

2 Charleston PL

Case

AB12 30B

07730944722

# Fault Report

Customer Name: Arthur	Date: 10/5/23
Customer Reference: 4056	Fitter: RB
Salesperson: MP	Salesperson called: Yes/No <input checked="" type="radio"/>
Blind Type and number:	Vert headrail
Fault Description:	1765 x 1005
Action to correct:	New h/rail in Brown with Rφ Draw
Problem fixed on site: Yes/No <input checked="" type="radio"/>	
Further action required:	Yes.