

Fault Report

Customer Name <i>Evelyn maddler</i>	Date; <i>15/10/24</i>
Customer Reference: <i>22667</i>	Fitter
Salesperson:	Salesperson called: Yes/No
Fault Description: <i>P. Fit pleat seems to have come loose</i>	
Action to correct: <i>Corrected.</i>	
Problem fixed on site: Yes/No	
Further action required:	