

Fault Report

Customer Name: Thomson	Date: 23-6-23
Customer Reference: 22549	Fitter: mc
Salesperson: Scot	Salesperson called: Yes/No
Blind Type and number: Roll	
Fault Description: Too BIG	
Action to correct: TO BE CUT DOWN TO 3200 x 1425.	
Problem fixed on site: Yes/No <input checked="" type="radio"/>	
Further action required: Yes.	