

Fault Report

| | |
|--|---|
| Customer Name: <u>Sussams</u> | Date: <u>1/8/23</u> |
| Customer Reference: <u>22658</u> | Fitter: <u>mc</u> |
| Salesperson: <u>marzena</u> | Salesperson called: <input checked="" type="radio"/> Yes / <input type="radio"/> No |
| Blind Type and number: | <u>Verd headrail</u> |
| Fault Description: <u>Mis Measure doo BIG .</u> | |
| Action to correct: <u>Cut Down do 1200 .</u> | |
| Problem fixed on site: Yes / <input checked="" type="radio"/> No | |
| Further action required: <u>Yes .</u> | |