

Fault Report

| | |
|---|------------------------------|
| Customer Name: 23082 | Date: 11/9/23 |
| Customer Reference: Smith | Fitter: MC |
| Salesperson: madin | Salesperson called: Yes (No) |
| Blind Type and number: Roll | |
| Fault Description: needs cut down | |
| Action to correct: cut down to 1680 recess | |
| Problem fixed on site: Yes (No) | |
| Further action required: Yes | |